

CUSTOMER SERVICE FACILITY



ROTORCRAFT SUPPORT, INC.

Fillmore, California, USA

Has satisfactorily met all specified requirements to qualify as a Bell Approved Independent Customer Service Facility for the following Bell helicopters:

Listed Products

Field Maintenance:	205 / 206A / 206B / 206L / 212 / 222 / 407 / 412 / 429 / 505
Component Overhaul:	205 / 206A / 206B / 206L / 212 / 407 / 412 / 505
Cabin Repair:	206A / 206B / 206L
Tailboom Repair:	205 / 206A / 206B / 206L / 212 / 412



Michael Thacker

Michael Thacker
Executive Vice President, Innovation &
Commercial Business

Effective: August 1, 2020

Expires: June 30, 2021