

# CUSTOMER SERVICE FACILITY



## ROTORCRAFT SUPPORT, INC.

Fillmore, California

Has satisfactorily met all specified requirements to qualify as a Bell Approved Independent Customer Service Facility for the following Bell helicopters:

### Listed Products

Field Maintenance: 205 / 206A / 206B / 206L / 212 / 222 / 407 / 412 / 429 / 505 / Huey II  
Component Overhaul: 205 / 206A / 206B / 206L / 212 / 407 / 412 / 505  
Cabin Repair: 206A / 206B / 206L  
Tailboom Repair: 205 / 206A / 206B / 206L / 212 / 412

### Parts

Distribution Territory Canada & United States



*Michael Thacker*

Michael Thacker  
Executive Vice President, Innovation &  
Commercial Business

Effective: July 1, 2021

Expires: June 30, 2022

Revised: September 1, 2021