

CUSTOMER SERVICE FACILITY



Rotorcraft Support, Inc.

Van Nuys, California, USA

Has satisfactorily met all specified requirements to qualify as a Bell Approved Independent Customer Service Facility for the following Bell helicopters

Listed Products

Field Maintenance: 205 / 206A,B / 206L / 212 / 222 / 407 / 412 / 429 / 505 / OH-58A,C / UH-1H

Component Overhaul: 205 / 206A,B / 206L / 212 / 407 / 412 / OH-58A,C / UH-1H

Fuselage Repair Fixture: 206A,B / 206L

Tailboom Repair Fixture: 205 / 206A,B / 206L / 212 / 412 / UH-1H



SUSAN GRIFFIN
Executive Vice President, Commercial Business

Effective: March 1, 2016

Expires: February 28, 2019

Revised: April 16, 2018